MetroCount® traffic data specialists

RSU Status

MTE User Manual - Data Collection

4.03

MetroCount

Australia

15 O'Connor Close North Coogee WA 6163 Ph: 08 9430 6164 Fax: 08 9430 6187 Email: sales@metrocount.com

United Kingdom

Unit 15, Oliver Business Park Oliver Road Park Royal, London NW10 7JB Ph: 020 8782 8999 Fax: 020 8782 8737 Email: uksales@metrocount.com

United States

11820 West Market Place, Suite M Fulton MD 20759 Ph: 800 576 5692 Fax: 301 490 3521 Email: usasales@metrocount.com

www.metrocount.com



RSU Status

Overview

Clicking the **RSU Status** button on the main toolbar displays a snapshot of a RSU's current status, grouped into separate pages. It is advisable to do a status check regularly:

- Before setup to check remaining battery life.
- After setup to check the setup was successful, and the RSU is active.
- During a survey to monitor axle statistics and memory usage.

If a potential problem exists in any of the status pages, the relevant page will be automatically displayed, along with a warning message describing the problem.



Use the left and right arrow keys to step through the RSU Status pages.

Site Information

Note:

The Data page displays the survey parameters of the data currently in memory, as specified when the RSU was setup.

RS	U St	tatus - Char	inel 0	X
ſ	Data	RSU	Battery Hits Memory	
	Pr	operty	Value	^
		Site Name	001	
		Attribute	MetroCount HQ	
		Lane	00	
		Description	O'Connor Close north of Rollinson Rd	
		Layout	Axle sensors - Paired (Class/Speed/Count)	Ξ
		Direction A	7 - North bound A>B, South bound B>A. [7]	
		Direction B	0 - Unused or unknown. [0]	
		First Data	Unknown! (Roadside Unit start = 13:35 Wednesday, 14)	
		Last Data	Unknown! (Roadside Unit finish = 18:03 Monday, 19 Nov	
		Debounce	A=10ms, B=10ms	
		Spacing	1000 mm - 3 ft 3.4 in	-
		Anerstor	RC	
			Clos	e

RSU Site Information

RSU Activity

The **RSU** page displays information about the RSU's hardware, and the Status list at the bottom shows the RSU's current state of activity. It also lists recent events that may impact the data currently in memory, or the RSU's condition.

RSU Status - Cha	nnel 0
Data RSU	Battery Hits Memory
Property	Value
Ident.	? N200MPRS MC56-L5 [MC55] (c)Microcom 190ct04
RSU	MC5600
Batteries	Main=6.01, RAM=4.43, (M=6.01V, R=4.41V)
Memory	Used=11.03% (229451 of 2080768) [HI=0f, LO=404b]
	13:35 Wednesday, 14 November 2007
Start Time	13:35 Wednesday, 14 November 2007
	18:03 Monday, 19 November 2007
Run Time	5 days 4 hr 28 min
Status	[0x81] Roadside Unit ACTIVE: Running normally
✓	DATA available to unload
•	4
	Close


RSU status information

Text	Description
Roadside Unit not ACTIVE	The RSU is in its idle state.
Roadside Unit ACTIVE: Waiting for start time	The RSU has been setup with a deferred start time. When the start time is reached the RSU will switch to its active state.
Roadside Unit ACTIVE: Running normally	The RSU is in its active state, logging data.
DATA available to unload	The RSU contains data that has not been unloaded. This will remain until the RSU is stopped.
Memory FULL	The RSU has filled to capacity, and will have stopped logging data.
Main battery ran down	The RSU will switch to its idle state if the main battery drops below a certain level. This ensures that there is always sufficient power to communicate, barring battery failure. This message indicates the RSU may have stopped logging sooner than expected.
Roadside Unit POWER was interrupted	Power was interrupted while the RSU was active. If power is interrupted the RSU will stop logging data.
Dropped to IDLE (No hits)	The RSU stopped logging because no hits were detected for seven days.

Battery Levels

Non-rechargeable Main Battery

For RSUs with a non-rechargeable battery pack, the RSU Status gives an estimated number of days of continuous use, until the pack will need to be replaced. This estimate is based on the typical discharge curve for a battery pack supplied by MetroCount.



RSU battery status

When the battery voltage enters the yellow region of the graph, a reminder to replace the pack will be issued. Once in the red region, the battery should be replaced before any further use.

RSU Status - Channel 0		
Data RSU 🕂 Battery Hit		
Main battery 6.5 Main battery - re	splaceable alkaline cells	
Hmm Main ba	attery getting low!	
	Object: Main battery	_
5.19 5.0	Details: Replace soon!	*
		-
	Close	

Battery warning message

Even if the voltage is in the red region, the battery pack still has sufficient power for the RSU to communicate, unload any data, and retain data almost indefinitely. The RSU will automatically shutdown below the red region to ensure communication will still be possible.

Some RSUs have a separate RAM backup battery to retain the RSU's memory while the main battery is changed. This is automatically charged from the main battery.

Rechargeable Main Battery

To ensure optimal capacity and service life, RSUs with rechargeable main batteries should have their battery voltage kept in the green region at all times. Actual days of use between charging will vary depending on the age of the battery.

RSU battery status (rechargeable)

Running the main battery down to the red zone may result in irreversible damage to the battery, and it will probably need to be replaced.

Memory Usage

RSUs dedicate their entire memory to the current survey, and data must be unloaded onto a PC before the next setup. The RSU's Operator Guide lists an approximate hit capacity for each RSU memory size. Obviously the higher the traffic volume at a site, the shorter the survey that can be conducted. Once full, a RSU will stop logging data, and return to its idle state.

A RSU's status reports the percentage of capacity used so far, and an approximate time remaining until full. This is simply extrapolated from the amount of data logged and the Run Time (time elapsed since the RSU was setup).

RSU Status - Channel 0
Data RSU Battery Hits Memory
Total memory 2080768 bytes
Used so far 229451 bytes (11.03%)
Memory used
11%
Estimated time to run 1004 hr
Estimated full time 10:16 Wednesday, 26 December 2007
Close

Checking memory usage

When checking a RSU's status, warning messages will be issued if the unit is more than 90% full.

RSU Status - Channel 0 Data RSU Battery Hits Memory Total memory 2080768 bytes	
Used so far 2015232 bytes (96.85%)	Hmm
Memory used	Low memory! Object: Memory Details: Memory is more than 90% full.
Note: The following are estimates only Confidence 96.85% Estimated time to run 35 hr Estimated full time 03.32 Friday, 16 November 2007	

Memory usage warning message

Sensor Statistics

The Sensor or Hit statistics can be used as a rough guide to the quality of raw data logged by a RSU.

Data RSU Battery	Hits Memory	
Property	Value	
Total A Hits	47802	
Registered A Hits	47802 (100%)	
Rejected A Hits	0 (0%)	
Total B Hits	47802	
Registered B Hits	47802 (100%)	
Rejected B Hits	0 (0%)	
Total Ratio A/B	100%	
Registered Ratio A/B	100%	
Analysis	0 1 1 1 1 1 58	
	Sensors are matched within 5%	
٠	III	•

Checking sensor hits

Parameter	Description
Totals	The sensor Total counts are the total number of hits detected by each sensor. Registered represents the actual number of hits stored in memory.
Ratios	Ratios between the number of hits on each sensor.
	Conclusions and warnings related to the sensor totals and ratios. Warnings will only be issued if there is at least 200 axle hits on both sensors.

When using a Classifier Sensor Layout, a 100% match between A and B sensor hits is ideal. In reality, there will be a slight difference due to extra or missed hits.

A variation in total counts of more than 5% will give a **Sensor Imbalance** warning, highlighting a potential sensor problem at some point during the survey. The best way to examine if a problem with data quality exists is to unload the data and examine a plot of sensor hits, to determine where the mismatch occurred. For example, if a sensor problem started late in a survey, and there is sufficient usable data at the start, then the mismatch is not an issue.

Property	Value	Hmm
Total A Hits	47802	
Registered A Hits	47802 (100%)	Sensor imbalance!
Rejected A Hits	0 (0%)	
		Object:
Total B Hits	45242	Sensors
Registered B Hits	45242 (100%)	Details:
Rejected B Hits	0 (0%)	There may be a problem with sensor balance! Please check count details.
Total Ratio A/B	106%	
Registered Ratio A/B	3 106%	ОК
Analysis		
<i>0</i>	There is more th	an 5% mismatch between sensors
4		

Sensor imbalance warning

A Sensor Imbalance warning may also be triggered if more than 10% of the total hits are being removed by the debounce filter. For example, this can be caused by an incorrectly installed sensor, or vehicles traversing the sensors at an angle, giving multiple, closely-spaced hits. Again, it is simply a warning that there is something unusual about the data.

ata RSU Battery	Hits Memory
Property	Value
Total A Hits	47802
Registered A Hits	47802 (100%)
Rejected A Hits	0 (0%)
Total B Hits	57427
Registered B Hits	47616 (82.9%)
Rejected B Hits	9811 (17.1%)
Total Ratio A/B	83.2%
Registered Ratio A/B	100%
Analysis	
Ø	There is more than 16% mismatch between sensors
ø	More than 10% of sensor hits are being removed b.

Rejected hits warning

www.metrocount.com

Copyright© 1991, 2013 Microcom Pty Ltd. All rights reserved. MetroCount, Traffic Executive, MCSetup, MCSetLite, MCReport, MCTools, Microcom and Microcom Pty Ltd, and the MetroCount and Microcom Pty Ltd logo, are trademarks of Microcom Pty Ltd. All other trademarks are the property of their respective owners. Other Microcom intellectual property including Patents and designs may be protected by international law. The furnishing of this software, the accompanying product or any related documentation or materials does not give you any license to this intellectual property.